How to update the updater does not recognize NGCHDMI, it may be caused by the lack of CH340 driver, please follow the following tutorial to install the driver

1. Unzip the CH340 Drive package

2. Click run setup.exe

名称	修改日期	类型	大小
📁 DRVSETUP64	2023/1/8 13:26	文件夹	
📄 CH341PT.DLL	2022/11/22 11:13	应用程序扩展	7 KB
📄 CH341S64.SYS	2022/11/22 11:13	系统文件	59 KB
📄 CH341S98.SYS	2022/11/22 11:13	系统文件	20 KB
📄 ch341SER.CAT	2022/11/22 11:13	安全目录	11 KB
📄 CH341SER.INF	2022/11/22 11:13	安装信息	7 KB
📄 CH341SER.SYS	2022/11/22 11:13	系统文件	41 KB
📄 CH341SER.VXD	2022/11/22 11:13	虚拟设备驱动程序	20 KB
📄 SETUP.EXE	2022/11/22 11:13	应用程序	98 KB

3.Click Install and wait for the installation to complete, then you can update the converter program with NGC HDMI Updater